

GreenStar® Repairs



Original GreenStar® Display

Description	List Price
Audio Alarm, Keypad, Backlight, LCD Vertical Line Repair	200.00

Receivers

Description	List Price
StarFire® Generation 2 Receiver Repair	500.00
StarFire® iTC® Receiver Repair	500.00
StarFire® iTC® Receiver Repair and Replace Case	750.00
StarFire® 3000 Receiver Repair	500.00
StarFire® 3000 Receiver Repair and Replace TCM	950.00
StarFire® 3000 Receiver Repair and Replace Case	900.00

RTK Radios

Description	List Price
900 MHz Radio Repair	250.00
450 MHz Radio Repair	Call

GreenStar® units on page 1 can be repaired at ALL Locations. However - the GreenStar® units on page 2 can *only* be repaired → at our Indiana location. Please forward to:



**Ag Express Electronics
106 W. Main St.
Sulphur Springs, IN 47388**

**For Questions, please call: (765) 533-4809
Or email: ss@agexpress.com**