

# Case New Holland® Repairs

- AFS® Universal Display Plus
- AFS® Pro700 Display
- AFS® Pro600 and IntelliView™ Display

[www.agexpress.com](http://www.agexpress.com)



- EZ-Guide® Series Lightbars
- Autopilot™ Components
- EZ-Steer® Controllers and Motors

[www.agexpress.com](http://www.agexpress.com)

## AFS® Pro 700 and New Holland® IntelliView IV™

Description	Typical Repair Price (List)
Audio Alarm Repair	150.00
Backup Battery Replacement	150.00
USB Port Repair	185.00
Console Connector Replacement	225.00
Touch Screen Replacement	800.00
LCD Replacement	800.00

## AFS® Pro 600 and New Holland® IntelliView™

Description	Typical Repair Price (List)
Audio Alarm Repair	150.00
Backup Battery Replacement	150.00
Display Backlight Repair	150.00
Console Connector Replacement	225.00
Card Reader Repair	380.00
Touch Screen Replacement	600.00
LCD and Touch Screen Replacement (see note 1)	1200.00

## AFS® Universal Display Plus

Description	Typical Repair Price (List)
Audio Alarm Repair	150.00
Console Connector Replacement	200.00
Card Reader Repair	380.00
Touch Screen Replacement	650.00
LCD and Touch Screen Replacement (see note 1)	1450.00

Note 1: To replace defective LCD assemblies on these units, it is necessary to replace the Touch Screen assembly as well. The repair price reflects the List price to replace both assemblies.