

GreenStar® Repairs



Original GreenStar® Display **Note** ⇒ Originals are repaired at our Indiana location only

| Description | List Price |
|--|------------|
| Audio Alarm, Keypad, Backlight, LCD Vertical Line Repair | 200.00 |

Receivers **Note** ⇒ Receivers are repaired at our Indiana location only

| Description | List Price |
|---|------------|
| StarFire® Generation 2 Receiver Repair | 500.00 |
| StarFire® iTC® Receiver Repair | 500.00 |
| StarFire® iTC® Receiver Repair and Replace Case | 750.00 |
| StarFire® 3000 Receiver Repair | 500.00 |
| StarFire® 3000 Receiver Repair and Replace TCM | 950.00 |
| StarFire® 3000 Receiver Repair and Replace Case | 900.00 |

RTK Radios **Note** ⇒ RTK Radios are repaired at our Indiana location only

| Description | List Price |
|----------------------|------------|
| 900 MHz Radio Repair | 250.00 |
| 450 MHz Radio Repair | Call |

GreenStar® units on page 1 can be repaired at ALL Locations. However - the GreenStar® units on page 2 can *only* be repaired → at our Indiana location. Please forward to:



Ag Express Electronics
106 W. Main St.
Sulphur Springs, IN 47388

For Questions, please call: (765) 533-4809
Or email: ss@agexpress.com