

# Trimble® Repairs



## Rawson® Controllers and Drives

Description	Typical Repair Price (List)
PAR E Hydraulic Motor Assembly	750.00 - 1000.00
PAR 4 Hydraulic Motor Assembly	750.00 - 1000.00
PAR 2 Hydraulic Motor Assembly	750.00 - 1000.00
Mark III Input	335.00 - 385.00
Mark III Processor	295.00 - 395.00
AccuPlant™ Processor	295.00 - 395.00
Mark IV Processor	295.00
AccuRate™ Processor	295.00

**Note: Repair prices are shown for reference only. All Trimble® repair customers are provided with an estimate prior to repair.**



Repair for Trimble® Navigation Equipment is offered *only* at our →Iowa location.

Please forward to:



Ag Express Electronics  
6280 NE 14<sup>th</sup> Street  
Des Moines, Iowa 50313

For Questions, please call: (515) 289-2746  
Or email: [ht@agexpress.com](mailto:ht@agexpress.com)